

**SOUTH DAYTON DUMP
1976 SPRINGBORO ROAD
MORAINE 45439
557-0752**



FILE INDEX

LAST UPDATED: 7-23-01

- File Index
- PA File
- Field Notes
- STEP Workplan/Report
- Montgomery County Health Department File Info
- STEP Groundwater Screening Sampling Results/February 1996
- Site Access
- LOE Invoices 12/95
- Installation of Groundwater Monitoring Wells
PSARA Technologies
June 1996
- Site Specific QAPP
PSARA Technologies
January 1996
- Site Specific Health & Safety Plan
PSARA Technologies
December 1995
- Final Work Plan
PSARA Technologies
January 8, 1996
- **CONFIDENTIAL**
- **CONFIDENTIAL** HRS Score Package for STEP
- LOE Invoices 3/96

South Dayton Dump
File Index
Page 2

- Analytical Data 1991
- Final Screening Site Inspection Report/9-23-91
- **CONFIDENTIAL** Draft Screening Site Inspection Report/July 9, 1991
- STEP Analytical Results
- Maps, Aerial Photos, Drawings, Report Figures
- Well Logs